



Product News & Information for Stores

Bulletin #: CQ11-06 - CARQUEST 94206
Customer: All CARQUEST Customers
Date: November 28, 2016
Subject: 94206 Installation Instructions

This is a response to recent inquiries from the field for clarification about the proper installation of the cartridge filter for the 2014-17 Jeep Grand Cherokee V6 Diesel and 2014-17 Ram 1500 Pickup V6 Diesel vehicles. The filter meets OE requirements and it fits perfectly when installed properly. Please review the instructions below that outline the proper installation for this part.

Closed Gap
(Fully seated)

Proper Installation
(Fully seated)



Proper Filter Installation

Once the cap O-ring is fully inserted into the housing, the filter must be inserted another 0.360" for full seating of the gasket of the filter element.

If the cap is not fully seated, the element O-ring may not be inserted deeply enough to create a full-seal and this can cause oil to leak from the unit. Please note, hand tightening the cap does not allow for proper, full-insertion due to the amount of torque required for this process. For proper installation, use a torque wrench to tighten filter cap to 25 Nm.

Open Gap
(Not seated)

Improper Installation
(Not seated)

